

WORKMASTER™ BOOTS SIZING CHART


FOR PRINTING ON A3 PAPER

Sizes (EU / UK)		Sizes (EU / UK)
50 / 15		50 / 15
46 / 12		46 / 12
45 / 11		45 / 11
44 / 10		44 / 10
43 / 9		43 / 9
42 / 8		42 / 8
41 / 7		41 / 7
39 / 6		39 / 6
37 / 5		37 / 5
35 / 3		35 / 3

Instructions for use:

- 1. Print this A3 PDF at 'Actual Size' (100% scale), do not select 'fit', 'Shrink oversized pages' or Custom scale'
- 2. Check the sizing buy measuring the calibration cube below - if it does not measure 3cm square check your print settings and re-print
- 3. Fold the page at the dotted line at the bottom of the page so that the image of the foot is at the edge of the page
- 4. Put this edge against a wall and place your socked foot on the page with your heel against the wall
- 5. Your Workmaster boots size can be read off from the scale - Use the size that appears underneath the line immediately in front of your big toe

Calibration Cube



Size: EU	35	36	37	39	41	42	43	44	45	46	47	49	50
UK	3	4	5	6	7	8	9	10	11	12	13	14	15
Max. Internal Length (mm)	237	240	251	266	276	287	292	297	304	316	318	323	326
Max. Internal Width (mm)	83	83	85	90	90	93	93	97	97	101	101	101	101



..... Fold Here